

03500.015865



Cafe 8
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
TOMOYA YONEDA ET AL.) : Examiner: Luong T. Nguyen
Appln. No.: 09/973,054) : Group Art Unit: 2612
Filed: October 10, 2001) :
For: IMAGE PICKUP APPARATUS) :
U.S. Patent No.: 6,952,228 B2) :
Issued: October 4, 2005) : January 11, 2006

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Certificate
JAN 19 2006
of Correction

01/12/2006 SZEWIDIE1 00000140 6952228

01 FC:1811

100.00 OP

CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

JAN 20 2006

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



John A. Krause
Attorney for Patentees
Registration No. 24,613

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

544270v1

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,952,228 B2
DATED : October 4, 2005
INVENTOR(S) : TOMOYA YONEDA ET AL.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 6

FIGURE 6, "HORISONTAL" should read --HORIZONTAL--.

COLUMN 4

Line 56, "regained" should read --retained--; and
Line 57, "form" should read --from--.

COLUMN 5

Line 26, "pulses, of" should read --pulses, reset pulses and transfer pulses for controlling on/off of--; and
Line 63, "dnd" should read --and--.

COLUMN 6

Line 14, "VKLC1," should read --VCLK1,--;
Line 31, "VKLC1," should read --VCLK1,--; and
Line 60, "VKLC1" should read --VCLK1--.

COLUMN 7

Line 36, "photoecharges" should read --photocharges--.

COLUMN 11


Line 9, "pick up" should read --pickup--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,952,228 B2

No. of add'l. copies
@ 30¢ per page



JAN 20 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,952,228 B2
DATED : October 4, 2005
INVENTOR(S) : TOMOYA YONEDA ET AL.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14

Line 4, "lense" should read --lens--;
Line 15, "is" should read --are--;
Line 28, "divining" should read --defining--;
Line 42, "lense 111" should read --lens 111--; and
Line 49, "lense 111" should read --lens 111--.

COLUMN 15

Line 43, "reading" should read --reading---.

COLUMN 16

Line 6, "lense" should read --lens--; and
Line 18, "is" should read --are--.

COLUMN 17

Line 10, "lense" should read --lens--.

COLUMN 18


Line 2, "lense" should read --lens--;
Line 9, "reading out" should read --reading-out--;
Line 23, "lense" should read --lens--; and
Line 51, "passed" should read --passes--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,952,228 B2

No. of add'l. copies
@ 30¢ per page



JAN 20 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,952,228 B2

DATED : October 4, 2005

INVENTOR(S) : TOMOYA YONEDA ET AL.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 19

Line 16, "AID" should read --A/D--; and

Line 51, "solid-sate" should read --read-solid-state--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,952,228 B2

No. of add'l. copies
@ 30¢ per page



JAN 20 2006

STAPLE
HERE
ONLY

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,952,228 B2

DATED : October 4, 2005

INVENTOR(S) : TOMOYA YONEDA ET AL.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 6

FIGURE 6, "HORISONTAL" should read --HORIZONTAL--.

COLUMN 4

Line 56, "regained" should read --retained--; and

Line 57, "form" should read --from--.

COLUMN 5

Line 26, "pulses, of" should read --pulses, reset pulses and transfer pulses for controlling on/off of--; and

Line 63, "dnd" should read --and--.

COLUMN 6

Line 14, "VKLC1," should read --VCLK1,--;

Line 31, "VKLC1," should read --VCLK1,--; and

Line 60, "VKLC1" should read --VCLK1--.

COLUMN 7

Line 36, "photoecharges" should read --photocharges--.

COLUMN 11

Line 9, "pick up" should read --pickup--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,952,228 B2

No. of add'l. copies
@ 30¢ per page



JAN 6 2000

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : 6,952,228 B2
DATED : October 4, 2005
INVENTOR(S) : TOMOYA YONEDA ET AL.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14

Line 4, "lense" should read --lens--;
Line 15, "is" should read --are--;
Line 28, "divining" should read --defining--;
Line 42, "lense 111" should read --lens 111--; and
Line 49, "lense 111" should read --lens 111--.

COLUMN 15

Line 43, "reading" should read --reading---.

COLUMN 16

Line 6, "lense" should read --lens--; and
Line 18, "is" should read --are--.

COLUMN 17

Line 10, "lense" should read --lens--.

COLUMN 18

Line 2, "lense" should read --lens--;
Line 9, "reading out" should read --reading-out--;
Line 23, "lense" should read --lens--; and
Line 51, "passed" should read --passes--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,952,228 B2

No. of add'l. copies
@ 30¢ per page



JAN 20 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,952,228 B2

DATED : October 4, 2005

INVENTOR(S) : TOMOYA YONEDA ET AL.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 19

Line 16, "AID" should read --A/D--; and

Line 51, "solid-sate" should read --read-solid-state--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,952,228 B2

No. of add'l. copies
@ 30¢ per page



JAN 20 2006